315 E. 39th Street

Kansas City, Missouri 64111

REUSE ASSESSMENT

| | SITE ASSESSMENT | MARKET ASSESSMENT | COMMUNITY FEEDBACK | OVERALL APPROPRIATENESS | DISPOSITION ALTERNATIVES (L)EASE) / (S)ALE |
|---------------------|-----------------|-------------------|--------------------|----------------------------|--|
| EDUCATION | 3 | 3 | 4 | 3 | L or S |
| Elementary | | 3 | | | |
| Middle/High | 3 | 3 | 4 | | |
| Post-secondary | 3 | 3 | 4 | | |
| RESIDENTIAL | 3 | 4 | 3 | 3 | S |
| Market Rate | 3 | 3 | | | |
| Affordable | 3 | 4 | | | |
| Senior | 3 | 3 | | | |
| Mixed-Income | 3 | 4 | | | |
| New Construction | 4 | 4 | | | |
| COMMERCIAL | 2 | 3 | 3 | 3 | L or S |
| Office | 3 | 3 | | | |
| Retail | 1 | | | | |
| COMMUNITY USE | 1 | 2 | 4 | 2 | L or S |
| Community Center | | | | | |
| Open Space | | | | | |
| Community Garden | | | | | |
| MIXED USE | 4 | 4 | 4 | 4 | L or S |
| | | | | | |
| | | | | | |
| DEMOLISH | 1 | 1 | 1 | 1 | S |

Scale: 1-5, 5 being highest

COMMUNITY FEEDBACK (Site visit April 16, 2011): Participants indicated that both Westport Middle and High are symbols of and gateways to the neighborhood, and that their reuse could serve as the engine to inspire reinvestment in the area. Participants identified multiple reuses that would benefit the neighborhood including education (college extension, adult education, K-12 school, community arts/theater), housing, community center, multiple uses/organizations.



BUILDING/SITE ASSESSMENT: Building is in fair condition; however, its very large size may pose an impediment to reuse. Its layout is readily adaptable for multi-family housing (70 +/- units). Classroom size converts well into a single bedroom apartment or combines well into to two bedroom apartments. The large square footage dedicated to the auditorium, gymnasiums, and library do not support reuse solely as a multi-family residence. In addition, the number and configuration of stairs and exits support division of the building for multiple tenants (such as housing + community services/office). The building's exterior and interior design limit the visibility required for good retail use. The building location and layout support office use, but it is extremely large for reuse of this nature. While condition may be a deterrent to reuse as a school, the facility is ideally suited for secondary or post-secondary educational use. There is only partial air conditioning, which will limit reuse options under a short-term lease scenario. Uses other than office or education will typically require installation of a fire sprinkler system (a community center may also be exempt depending on overall sq. footage and location of exits). Property includes open land east and south of the building as well as a parking lot across McGee Street that could be developed with additional parking (if needed) and/or new construction.

<u>HISTORIC ASSESSMENT:</u> Building is a good example of an early 20th century Progressive Era high school. Alterations to the original layout, finishes and features have been minimal, and additions constructed at the rear of the building in 1964 and 1992 respect the original building in placement, massing, and materials. The building appears eligible for listing in the National Register.

MARKET ASSESSMENT: The site is centrally located in the heart of Midtown, has great access both from a vehicular and pedestrian perspective, and is within walking distance of the Main Street commercial district and the MAX bus line. The area has a mix of single and multi-family housing, and is more than 70% renteroccupied. The area has seen significant reinvestment, both along the Main Street commercial corridor and with residential development on Armour Blvd. While the size of the building may present some challenges, it does offer opportunities for entities looking for substantial square footage. At over 9 acres, with an adjacent parking lot with commercial zoning, the site presents opportunities for entities looking for open space or in need of parking/room to expand.

LAND-USE AND ZONING ASSESSMENT: Land-use surrounding Westport High is primarily single-family residential and neighborhood commercial. The current R-1.5 and R-2.5 zoning classifications for the school site support a variety of potential reuses, including education, community center, and certain residential uses. Commercial reuses would require rezoning unless the building receives national or local historic designation. Higher density residential reuse would also require rezoning. The satellite parking lot's entire northern half is zoned B3-2 (large scale community business) with the lower half divided between R-1.5 (SE corner) and R-2.5 (SW corner) single family residential zoning.

15 September 2011 Westport High - 1

315 E. 39th Street

Kansas City, Missouri 64111

This size of classroom converts well into a single bedroom apartment or Typical classroom size is 800 SF. combines well into two bedroom

Large operable windows allow natural light and ventilation apartments

access and includes an additional lot Parking is sufficient with easy across the street

Paint is peeling in a number of areas Large gymnasiums and auditorium in good condition

Multiple areas of vandalism on

Ceilings typically have numerous damaged or missing tiles exterior and interior

separation between lower floors and multiple uses, for example it could be divided vertically into multiple areas or horizontally providing Building could be divided into

upper floors KEY NOTES

Gymnasium #1 - glazed brick and

Cafeteria - VCT floor with acoustical plaster walls, wood floors, and steel Si

Offices - non-historic finishes and configuration grid ceiling က

Glazed wall at main entrance

Omate finishes at main entrance

Auditorium - sloped floor, attached File floor with marble columns seating, raised stage, beamed

Typical entrance - glazed brick ceiling, omate plaster work ထ

Library - modern finishes, acoustica walls, concrete stairs <u>ග</u>

Typical corridors - concrete floors,

and chair rail, acoustical ceiling grid Typical classroom - composite tile glazed brick walls, built-in lockers floor, plaster walls, wood casings

12. Gymnasium #2 - wood floor, plaster

plaster walls, acoustical ceiling grid, 13. Typical classroom - VCT floor, no trim

 Typical stair - concrete, metal railing, glazed brick walls, mosaic tile art on

Ground

c. 1964 ADDITION c. 1992 ADDITION Graffiti on building exterior Peeling paint at ceiling Hole in wood floor (2) CONDITION NOTES Graffiti in stairwell **Broken window ⋞**⋴сы CIRCULATION HORIZ. **BUILDING SERVICES** CIRCULATION VERT POSSIBLE LOCATION SEPARATION IN MULTI-USE SCENARIO RESTROOMS FOR TENANT **AUDITORIUM ADMINISTRATION** MULTI-USE SENARIO SHARED EXIT STAIR IN CLASSROOMS GYMNASIUM CAFETERIA MEDIA





DEVELOPMENT INITIATIVES











15 September 2011 Westport High - 2

315 E. 39th Street

Kansas City, Missouri 64111

This size of classroom converts well into a single bedroom apartment or Typical classroom size is 800 SF. combines well into two bedroom apartments

Graffiti on building exterior

⋞⋴сы

CIRCULATION HORIZ. **BUILDING SERVICES**

CIRCULATION VERT.

CAFETERIA

MEDIA

Hole in wood floor

CONDITION NOTES Graffiti in stairwell

AUDITORIUM

ADMINISTRATION CLASSROOMS

Peeling paint at ceiling


Broken window

- Large operable windows allow Parking is sufficient with easy natural light and ventilation
- access and includes an additional lot across the street
 - Large gymnasiums and auditorium in good condition
- Paint is peeling in a number of areas Multiple areas of vandalism on exterior and interior
 - Ceilings typically have numerous damaged or missing tiles
- separation between lower floors and multiple uses, for example it could be divided vertically into multiple areas or horizontally providing Building could be divided into upper floors

KEY NOTES

- plaster walls, wood floors, and steel Gymnasium #1 - glazed brick and
- Cafeteria VCT floor with acoustical grid ceiling Si
 - Offices non-historic finishes and configuration က

 - Omate finishes at main entrance Glazed wall at main entrance
- Auditorium sloped floor, attached File floor with marble columns seating, raised stage, beamed
- Typical entrance glazed brick ceiling, omate plaster work ထ
- Library modern finishes, acoustica walls, concrete stairs <u>ග</u>
 - Typical corridors concrete floors, ceiling grid
- and chair rail, acoustical ceiling grid Typical classroom - composite tile glazed brick walls, built-in lockers floor, plaster walls, wood casings
- 12. Gymnasium #2 wood floor, plaster 13. Typical classroom - VCT floor,
- plaster walls, acoustical ceiling grid, no trim
- Typical stair concrete, metal railing, glazed brick walls, mosaic tile art on



15 September 2011 Westport High - 3

315 E. 39th Street

Kansas City, Missouri 64111

This size of classroom converts well into a single bedroom apartment or Typical classroom size is 800 SF. combines well into two bedroom apartments

Graffiti on building exterior

⋞⋴сы

CIRCULATION HORIZ. **BUILDING SERVICES**

CIRCULATION VERT

RESTROOMS

GYMNASIUM CAFETERIA

Hole in wood floor

CONDITION NOTES Graffiti in stairwell

AUDITORIUM

Peeling paint at ceiling

Broken window

access and includes an additional lot Large operable windows allow Parking is sufficient with easy natural light and ventilation

Large gymnasiums and auditorium in good condition across the street

Paint is peeling in a number of areas Multiple areas of vandalism on exterior and interior

Ceilings typically have numerous damaged or missing tiles

separation between lower floors and multiple uses, for example it could be divided vertically into multiple areas or horizontally providing Building could be divided into upper floors

KEY NOTES

plaster walls, wood floors, and steel Gymnasium #1 - glazed brick and

Cafeteria - VCT floor with acoustical Offices - non-historic finishes and grid ceiling Si က

Glazed wall at main entrance configuration

Omate finishes at main entrance

Auditorium - sloped floor, attached File floor with marble columns seating, raised stage, beamed

Typical entrance - glazed brick ceiling, omate plaster work ထ

Library - modern finishes, acoustica walls, concrete stairs <u>ග</u>

 Typical corridors - concrete floors, ceiling grid

and chair rail, acoustical ceiling grid Typical classroom - composite tile glazed brick walls, built-in lockers floor, plaster walls, wood casings

12. Gymnasium #2 - wood floor, plaster walls, steel trusses

plaster walls, acoustical ceiling grid, 13. Typical classroom - VCT floor, no trim

 Typical stair - concrete, metal railing, glazed brick walls, mosaic tile art on

c. 1964 ADDITION MULTI-USE SCENARIO POSSIBLE LOCATION SEPARATION IN FOR TENANT (2) STAIR IN SHARED EXIT MULTI-USE SENARIO (<u>6</u> STAIR IN MULTI-USE SENARIO SHARED EXIT

ı



Second Floor













MEDIA

ADMINISTRATION

CLASSROOMS

315 E. 39th Street

Kansas City, Missouri 64111

This size of classroom converts well into a single bedroom apartment or Typical classroom size is 800 SF. combines well into two bedroom

Graffiti on building exterior

⋞⋴сы

CIRCULATION HORIZ. **BUILDING SERVICES**

CIRCULATION VERT

RESTROOMS

GYMNASIUM CAFETERIA

Hole in wood floor

CONDITION NOTES Graffiti in stairwell

AUDITORIUM

Peeling paint at ceiling

Broken window

Large operable windows allow natural light and ventilation apartments

access and includes an additional lot Parking is sufficient with easy across the street

Large gymnasiums and auditorium in good condition

Paint is peeling in a number of areas Multiple areas of vandalism on exterior and interior

Ceilings typically have numerous damaged or missing tiles

separation between lower floors and multiple uses, for example it could be divided vertically into multiple areas or horizontally providing Building could be divided into

upper floors KEY NOTES

plaster walls, wood floors, and steel Gymnasium #1 - glazed brick and

Cafeteria - VCT floor with acoustical Offices - non-historic finishes and grid ceiling Si က

Glazed wall at main entrance configuration

Omate finishes at main entrance Tile floor with marble columns

Auditorium - sloped floor, attached seating, raised stage, beamed ceiling, omate plaster work

Typical entrance - glazed brick walls, concrete stairs ထ

Library - modern finishes, acoustica ceiling grid


 Typical corridors - concrete floors, glazed brick walls, built-in lockers

and chair rail, acoustical ceiling grid 12. Gymnasium #2 - wood floor, plaster Typical classroom - composite tile floor, plaster walls, wood casings

13. Typical classroom - VCT floor, walls, steel trusses

plaster walls, acoustical ceiling grid, no trim

 Typical stair - concrete, metal railing, glazed brick walls, mosaic tile art on





Third Floor











15 September 2011

MEDIA

ADMINISTRATION CLASSROOMS

315 E. 39th Street

Kansas City, Missouri 64111

PHOTOGRAPHS



Exterior



Media Center



Auditorium



Gymnasium



Corridor



Classroom

15 September 2011 Westport High - 6